




## Summary of Fire Risk Assessment (HS019)

<b>Address</b>	Stephenson House
<b>Property Reference</b>	1739
<b>Survey Type Full or review</b>	Full
<b>Responsible Person</b>	Thirteen
<b>Surveyor</b>	Barry Waller
<b>Survey Date</b>	25th October 2018
<b>Date of Next Survey</b>	October 2019
<b>Surveyor Signature</b>	

<b>Type of Building/Premises</b>	Flats		
<b>Use of Premises</b>	Residential		
<b>Number of Floors</b>	3		
<b>Summary of last Survey</b>	<b>Category</b>	<b>Actions</b>	<b>Completed Actions</b>
	<b>Number of High Priority Actions</b>	0	0
	<b>Number of Medium Priority Actions</b>	1	1
	<b>Number of Low Priority Actions</b>	0	0

<b>Risk Rating</b>	<b>Current Rating</b>
Low Rating: 1 – 4 (low or very little risk from fire)	9
Medium Rating: 5 – 10 (possible risk of fire due to combustible materials present)	
High Rating: 11 – 16 (likelihood of fire due to large amounts of combustible material present)	
Extremely High Rating: 20 - 25 (Highly likelihood of fire due to large sources of combustible material in multiple places)	

**Note:**  
 If you come across any defects, please report all repairs through to our Customer Services Team on 0300 111 1000

For further information please e-mail the Building Safety Team: [BuildingSafetyTeam@thirteengroup.onmicrosoft.com](mailto:BuildingSafetyTeam@thirteengroup.onmicrosoft.com)

