




Summary of Fire Risk Assessment (HS019)

Address	Leighton Road
Property Reference	1894
Survey Type Full or review	Full
Responsible Person	Thirteen
Surveyor	Les Jones
Survey Date	8th May 2018
Date of Next Survey	May 2019
Surveyor Signature	

Type of Building/Premises	Low rise brick building		
Use of Premises	Young Persons Project		
Number of Floors	2 Floors		
Summary of last Survey	Category	Actions	Completed Actions
	Number of High Priority Actions	0	0
	Number of Medium Priority Actions	4	4
	Number of Low Priority Actions	0	0

Risk Rating	Current Rating
Low Rating: 1 – 4 (low or very little risk from fire)	9
Medium Rating: 5 – 10 (possible risk of fire due to combustible materials present)	
High Rating: 11 – 16 (likelihood of fire due to large amounts of combustible material present)	
Extremely High Rating: 20 - 25 (Highly likelihood of fire due to large sources of combustible material in multiple places)	

Note:
 If you come across any defects, please report all repairs through to our Customer Services Team on 0300 111 1000

For further information please e-mail the Building Safety Team: BuildingSafetyTeam@thirteengroup.onmicrosoft.com

