

Estate Walkabout

Walkabout:	Patch 4 J & K Blocks, Owton Manor	Date:	09.01.18	Neighbourhood Officer:	Joy Bishop
Attendees	None				
Roads covered	Owton Manor Lane, Jameson Road, Jura Gr, Jute Gr, Joppa Grove, Jarvis Walk, Jedburgh Road, Juniper Wk-Kinross Gr, Kintra Rd, Kinbrace Rd, Kirriemuir Rd, Kelso Gr, Kebock Wk, Kells Gr, Kelvin Gr, Kilmarnock Rd, Kilmory Wk-Kilsyth Gr-Kerr Gr.				

Location	Issue/Defect	Action Taken	Date Actioned	Issue Resolved Y/N & additional comments if further action needed
Owton Manor Lane	Void,	None	09.01.18	Will check on 16.01.18
Owton Manor Lane	Boundary wall knocked down. Windows boarded up.	Both booked to be repaired Jan 2018.	09.01.18	Continue to monitor.
Jameson Road	OK	None	09.01.18	Continue to monitor.
Jura Grove	Private vacant property, Garden overgrown coming into our property. Building in very poor condition. Bins over flowing.	Email photo to HBC	09.01.18	Continue to monitor.
Jute Grove	None	None	09.01.18	Will check on 16.01.18

Estate Walkabout

Location	Issue/Defect	Action Taken	Date Actioned	Issue Resolved Y/N & additional comments if further action needed
Joppa Grove	None	None	09.01.18	Will check on 16.01.18
Jarvis Walk	Void, check all ok. Alarm fitted.	OK	09.01.18	Will check on 16.01.18
Jarvis Walk	Fly tipping on path.	E mail sent to HBC	09..01.18	Will check on 16.01.18
Jedburgh Road	Grass verge pulled up.	Email sent to HBC, residents not happy with condition of grass.	09.01.18	Will check on 16.01.18
Jedburgh Road	Front window boarded up.	Chat with tenant. Happened when she was out.	09.01.18	Will check on 16.01.18
Juniper Walk	OK	None	09.01.18	Will check on 16.01.18
Kerr Grove	Fly tipping at the side of grass, top end.	Email photo to HBC	09.01.18	Will check on 16.01.18

Estate Walkabout

Kintra Road	OK	None	09.01.18	Will check on 16.01.18
Kinross Grove	Ok	None	09.01.18	Will check on 16.01.18
Kilmarnock Road	Rent arrears	Spoken to tenant, put through to Sue Waites to pay out standing arrears.	09.01.18	Will check on 16.01.18
Kirriemuir Road	Litter all over the street.	E mail sent to HBC.	09.01.18	Will check on 16.01.18
Kilsyth Walk	OK	None	09.01.18	Will check on 16.01.18
Area behind, St Patrick Shops in Owton Manor Lane	Fly tipping and shop trays scattered over the whole area.	E mail sent to HBC.	09.01.18	Will check on 16.01.18
Kinbrace Road	Side front window boarded up,	Checked repairs, booked for 16.01.18.	09.01.18	Will check on 16.01.18
Kilmarnock Road	Scaffold still up for repair.	E mail sent to repair line to have it removed.	09.01.18	Will check on 16.01.18

Estate Walkabout

Kerr Grove	PVC facer hanging down under no4.	Repair sent to repair line.	09.01.18	Will check on 16.01.18
Kelso Grove	None	None	09.01.18	Will check on 16.01.18
Kebock Walk	None	None	09.01.18	Will check on 16.01.18
Kells Grove	None	None	09.01.18	Will check on 16.01.18
Kelvin Grove	None	None	09.01.18	Will check on 16.01.18
Kilmory Walk	None	None	09.01.18	Will check on 16.01.18

Photographs

