

<b>Area</b>	Patch 4 M Block, Owton Manor	<b>Date:</b>	03.01.19	<b>Neighbourhood Officer:</b>	Joy Bishop
	Attendees, None				
	2.4.6.7.8.10.12Munro.Grove, 175a179,187,191,193,195,197,201,203,209,219,221,223,225,227,229,231,233,235,257..Owton..Manor..Lane, 2.4.6.8.10.12.14.16.17.18.23.27.31.35.40.41.44.45.46.47.48.50.51.53.55.57.61.63.65.67.6.69.70.71.73.78.80.82.88.94.Motherwell Road,2.4.6.7.8.9.10.11.13.14.16.18.19.20.21.23.25.28.31.37.39 Monkton Road,1.3.8.10.12.14.16.19.22.26.32.36.38.42 Malcolm Road, 1.2.3.4.5.6.7.8.9.10.11.12.13.15.17.18.19.20.21.22.23.25.27.2931.33.35.36.37.39.41.43.45.47.49.51.53.55.57.59.63.Maxwell Road, 1.2.3.Maxwell Court, 1.4.6.8.9.12.14.15.18.19.21.23.30.32.Macrae Road,3.7.8.10.12.Milne Walk,1.3.4.5.7.8.9.11.13.15. Muir Grove, 2.5.12.13.14.16.17.18.21.23.24.26.28.32.34.Mullroy Road, 2.4.6.7.8.9.11.12.13.14.15.16.18.19.20.22.23.28.32.Minch Road, 3.4.5.7.10.12.15.17.18.19.22.23.24.26.27.31.32.33.35.36.39.41.42.43.44.46.47.48.50.51.52.53.54.56.59.62.63.65.67.68.70.71.73.74.76.79.81.84.87.88.89.90.91.92.93.94.95.96.98.99.10 0.101.102.103.104.105.Moffat Road, 1.4.9.11.15.18.21.23.25.27.Midlothian Road, 2.3.4.6.7.8.10.11.12.13.14.15.16.17.18.19.20.22.24.25.26.27.28.30.32.Monach Road.				

<b>Location</b>	<b>Issue/Defect</b>	<b>Action Taken</b>	<b>Date Actioned</b>	<b>Issue Resolved Y/N &amp; additional comments if further action needed</b>
Monach Road	Settee in front garden	Check next week.	03.01.19	Will check on 10.01.19
Macrae Road	Void	No problems, all ok.	03.01.19	Will check on 10.01.19
Muir Grove	Construction work taking place.	All ok.	03.01.19	Will check on 10.01.19
Owton Manor Lane	Litter pick required on front of Shops.	Email sent to HBC	03.01.19	Will check on 10.01.19
Behind Monkton Road	Fly tipping next to substation.	Email sent to HBC	03.01.19	Will check on 10.01.19
Monkton Road	Both properties need the guttering cleaning out.	Reported to repair line ( Completed )	03.01.19	Will check on 10.01.19
Monkton Road	Ridge tile missing.	Reported to repair line ( Completed )	03.01.19	Will check on 10.01.19
Moffat Road	Door in front garden.	Check removed next week.	03.01.19	Will check on 10.01.19
Moffat Road	Wooden bed in front garden	Check removed next week.	03.01.19	Will check on 10.01.19

<b>Location</b>	<b>Issue/Defect</b>	<b>Action Taken</b>	<b>Date Actioned</b>	<b>Issue Resolved Y/N &amp; additional comments if further action needed</b>
Motherwell Road	Car parked on no	Spoken to mother, asked her to get tenant to ring me. Left a card.	03.01.19	Will check on 10.01.19
Motherwell Road	Fridge freezer in front garden.	Check removed next week.	03.01.19	Will check on 10.01.19
Motherwell Road	Fridge freezer in front garden.	Check removed next week.	03.01.19	Will check on 10.01.19
Munro Grove	None	Ok	03.01.19	Will check on 10.01.19
Wainfleet Drive	None	OK	03.01.19	Will check on 10.01.19
Maxwell Road	Construction work taking place. Barrier down to prevent kids climbing on it.	Photos taken	03.01.19	Will check on 10.01.19
Maxwell Road	Guttering full of grass, needs clearing.	Email sent to repair line	03.01.19	Will check on 10.01.19
Maxwell Court	None	OK	03.01.19	Will check on 10.01.19
Midlothian Road	Void	None	03.01.19	Will check on 10.01.19
Milne Walk	None	Ok	03.01.19	Will check on 10.01.19
Minch Road	Tenant in respite.	OK	03.01.19	Will check on 10.01.19
Malcolm Road	Wood in front garden.	OK	03.01.19	Will check on 10.01.19
Mullroy Road	Rubbish in front garden.	Check removed next week.	03.01.19	Will check on 10.01.19
Mullroy Road	Rubbish in front garden.	Check removed next week.	03.01.19	Will check on 10.01.19

**PHOTOS**

