thirteen

Managing and building homes

Glastonbury House Building Safety Service Schedule

From February 2025

Glastonbury House

Glastonbury House was built in 1968 and is a 16 storey / 45m tall building, with 91 rented general needs homes. It has one central staircase, six clearly signed fire exits, and a total floor area of 5800m².

Category:

Higher risk building - 2.

Details of construction:

Reinforced concrete floor and frame with a roughcast external finish. Refurbished in 2014 with over cladding of walls with an external wall system.

Heating type:

Commercial gas boiler.

Parking:

Disabled bays in close proximity of entrance doors, chevroned area for emergency vehicles, access to car park through road with a choice of two areas to park. Permit parking in operation.

Safety checks: 819 each year.

Number of fire doors within the building: 244.

Contact us

- www.thirteengroup.co.uk
- 300 111 1000
- Customerservices@thirteengroup.co.uk

Safety Checks

ТҮРЕ	FREQUENCY	RESPONSIBLE PERSON
Asbestos reg 4 (communal areas)	Annually	Head of Compliance Services
Booster pump	Quarterly	Head of Compliance Services
Building façade	Every two years	Head of Health & Safety
Calorifier water heater inspection	Quarterly	Head of Building Support Services
Closed circuit television	Bi-annually	Head of Compliance Services
Cold water storage inspections	Bi-annually	Head of Compliance Services
Commercial gas boiler	Bi-annually	Head of Compliance Services
Communal EICR	Every five years	Head of Compliance Services
Compartmentation survey	Every three years (under review)	Head of Health & Safety
Door entry access	Bi-annually	Head of Compliance Services
Dry riser (visual)	Annually	Head of Compliance Services
Dry riser (water pressure)	Annually	Head of Compliance Services
Emergency lighting (annual drain down)	Annually	Head of Compliance Services
Emergency lighting (monthly)	Monthly	Head of Compliance Services
Fire alarms (quarterly)	Quarterly	Head of Compliance Services
Fire alarms (weekly)	Weekly	Head of Building Support Services
Fire doors communal	Quarterly	Head of Health & Safety
Fire extinguisher	Annually	Head of Compliance Services
Fire risk assessment	Annually	Head of Health & Safety
Flat entrance fire doors	Annually	Head of Health & Safety
Generator back up (electrical load bank test)	Annually	Head of Compliance Services
Generator back up (mechanical certificate)	Bi-annually	Head of Compliance Services
Generators insurance	Annually	Head of Compliance Services
Laundry	Bi-annually	Head of Compliance Services
Lift A (LOLER)	Bi-annually	Head of Compliance Services
Lift A (maintenance)	Every two months	Head of Compliance Services
Lift B (LOLER)	Bi-annually	Head of Compliance Services
Lift B (maintenance)	Every two months	Head of Compliance Services
Lighting conductor	Annually	Head of Compliance Services
Maintenance fans	Quarterly	Head of Compliance Services
Plant room	Annually	Head of Compliance Services
Portable appliance test	Annually	Head of Compliance Services
Refuse room (chute damper)	Annually	Head of Compliance Services
Refuse room (suppression system)	Monthly	Head of Building Support Services
Rooftop inspection	Monthly	Head of Compliance Services
Smoke ventilation system	Bi-annually	Head of Health & Safety
Structural surveys	Every 15 years	Head of Health & Safety
Temperature monitoring	Monthly	Head of Compliance Services
Vehicle barriers	Bi-annually	Head of Compliance Services
Visual inspection of fire regulations equipment	Monthly	Head of Health & Safety
Water risk assessment		,
	Annually	Head of Compliance Services